

# Physics 259

## Uncertainties on DMM measurements


- During one day, we measured the *same* “100k” resistor with most of the Keithley DMMs
- Let’s recall what each of these measurements means
  - We have a TRUE value of the resistor  $R_0$
  - Each measurement is an *estimator* of the true value
  - Each measurement is a *sample* of size 1 that should reflect some probability density function  $P(R | R_0)$ 
    - This pdf is something the manufacturer knows – given a large group of their meters, if we measured the same value with each, what would the resulting distribution look like, and how much of a spread would there be between values.
- YOU only have 1 DMM
  - Your best *estimator* of the true value of the resistor is what the meter shows
  - Your *estimator* of the uncertainty on your estimate is based on the manufacturers data sheet, which encodes their pdf, in principle assuming a Gaussian distribution

# DMM uncertainties

- Here is the data

R(kOhms)

98.01  
 98.06  
 98.10  
 98.19  
 98.02  
 98.16  
 97.82  
 98.08  
 98.01  
 98.02  
 98.07  
 98.18  
 98.16  
 98.13  
 98.11  
 98.09



## DMM uncertainties

- The resistor was labeled 100k, and had 10% precision
- The *mean value* or *average* of our data is

$$\bar{R} = \frac{1}{N} \sum_{i=1}^N R_i = 98.08k\Omega$$

- This, by the way, is our best estimator for the true value of the resistor IF ALL THE MEASUREMENTS HAVE EQUAL UNCERTAINTY
- Before we talk about the uncertainty on this number, let's compare our data spread to the manufacturers claim

## DMM Uncertainties

- Recall we quantify the “width” of a distribution with its variance:

$$\begin{aligned}\sigma^2 &= E((x - \bar{x})^2) \\ &= E(x^2 - 2\bar{x}x + \bar{x}^2) \\ &= E(x^2) - 2\bar{x}E(x) + E(\bar{x}^2) \\ &= E(x^2) - 2\bar{x}^2 + \bar{x}^2 \\ &= E(x^2) - \bar{x}^2 \\ &= \overline{x^2} - \bar{x}^2\end{aligned}$$

- The Standard Deviation is just  $\sigma$

## DMM uncertainties

- For a finite sample of data, the variance (stdev squared) is, as defined above:

$$\begin{aligned}\sigma^2 &= \frac{1}{N} \sum_{i=1}^N (x_i)^2 - \left( \frac{1}{N} \sum_{i=1}^N x_i \right)^2 \\ &= \frac{1}{N} \left( \sum_{i=1}^N (x_i - \bar{x})^2 \right)\end{aligned}$$

- Now, a real subtlety to see if you have things straight:
- This is the variance of the given sample
  - We want something else – we want an estimator of the variance of the underlying probability distribution from which the sample was drawn
- The variance of the sample is NOT the best estimator of the true variance!

## Uncertainties of DMM

- For the *value* of the measurement, the mean of all measurements is the best estimator of the true value
- For the variance, or standard deviation, the right estimator is actually

$$\sigma_{est}^2 = \frac{1}{N-1} \left( \sum_{i=1}^N (x_i - \bar{x})^2 \right)$$

- Note the N-1, vs N
- If you use N, you have what is called a *biased estimator* – the average value of the estimator over many samples is not the true value

- Here is the data again, with the correct estimator of the mean and  $\sigma$

R(kOhms)

98.01

98.06

98.10

98.19

98.02

98.16

97.82

98.08

98.01

98.02

98.07

98.18

98.16

98.13

98.11


98.09

**Mean**      **98.08**

**Stdev**     **0.09**

- Our estimate of the true resistance: 98.08 kOhm
- Now let's estimate the uncertainty

# DMM uncertainty



R-Mean(kOhm)	(R-Mean)**2
-0.07	0.0043
-0.02	0.0002
0.02	0.0006
0.11	0.0131
-0.06	0.0031
0.08	0.0071
-0.26	0.0653
0.00	0.0000
-0.07	0.0043
-0.06	0.0031
-0.01	0.0000
0.10	0.0109
0.08	0.0071
0.05	0.0030
0.03	0.0012
0.01	0.0002

Kiethley:  $0.04\%+1d=0.05\text{kOhm}$   
 Our estimate dominated by one outlier ...


0.1236 SUM  
 0.0082 SUM/15  
 0.09 SQRT(kohm)

## Fitting with gnuplot

- Latest gnuplot is 4.2
- You should follow a tutorial and make sure you know how to plot a function, plot a data file, etc
- See the web page, help file, net ...
- You should feel comfortable plotting a function, plotting data points from a file and fitting the data points



## Fitting with gnuplot

- You will be fitting using the Least-Squares method (aka chi-squared fit)
- Suppose you have a set of data points, and each point's uncertainty  $\{x_i, y_i, \sigma_i\}$  in some file "chisq.dat"
- You can plot the data using gnuplot
  - plot "chisq.dat" using 1:2
  - plot "chisq.dat" using 1:2:3



# Fitting

- The data points alone don't tell the story
  - File "chisq.dat" has  $x$ ,  $y$ ,  $dy_1$ ,  $dy_2$ , where  $dy_1$  uncertainties vary point to point,  $dy_2$  are uniform:



- Your best estimate for the true value of the quantity measured will be different in these two cases
  - Quality of measurements must be taken into account!!

# Fitting



- To fit the data to a model, we postulate a functional form that the data points should follow
  - Eg might be an exponential + constant for the RC lab
- Form the  $\chi^2$  (chi squared) as follows:

$$\chi^2 = \sum_{i=1}^N \frac{(y_i - f(x_i | \vec{\theta}))^2}{\sigma_i^2}$$

- Where  $f$  is the value of your function at each point  $x$ , and  $\theta$  is the set of parameters of the function
  - Eg if  $f$  is a straight line,  $f(x)=m*x+b$ , the parameters are  $m$  and  $b$
- That is, take your *measured value* – *predicted value* at each point. Square these. Divide by the uncertainty on the point's measurements. Add all these up.
- The Least squares principle states that the best estimator for the function's parameters are those that minimize the  $\chi^2$

# Fitting

- Here are fits to a constant, using both uniform errors and non-uniform errors. Note these are different!



## Fitting a constant

- Let's do one fit by hand – fit data to a constant
  - This is like finding the mean of the data (weighted by errors).

$$\chi^2 = \sum_{i=1}^N \left( \frac{y_i - a}{\sigma_i} \right)^2 \quad f(x) = a \text{ is our fit function}$$

Find the minimum – set the derivative =0

$$0 = \frac{d\chi^2}{da} = -2 \sum_{i=1}^N \left( \frac{y_i - a}{\sigma_i^2} \right)$$

$$a \sum_{i=1}^N \frac{1}{\sigma_i^2} = \sum_{i=1}^N \frac{y_i}{\sigma_i^2}$$

$$a = \frac{\sum_{i=1}^N \frac{y_i}{\sigma_i^2}}{\sum_{i=1}^N \frac{1}{\sigma_i^2}} \quad \text{Weighted mean formula}$$

## Fitting a constant

- Note that if all the uncertainties are the same we get:

$$a = \frac{\sum_{i=1}^N \frac{y_i}{\sigma_i^2}}{\sum_{i=1}^N \frac{1}{\sigma_i^2}} = \frac{\frac{1}{\sigma^2} \sum_{i=1}^N y_i}{\frac{1}{\sigma^2} \sum_{i=1}^N 1} = \frac{1}{N} \sum_{i=1}^N y_i$$

- i.e. the usual MEAN value. The full formula properly weights the better measurements over the poorer ones.

## Degrees of freedom

- What do we expect the “typical” value of chisquared to be for a good fit?
- If the model fits the data, then each term in

$$\chi^2 = \sum_{i=1}^N \frac{(y_i - f(x_i | \vec{\theta}))^2}{\sigma_i^2}$$

Should be about 1 (by definition of the uncertainty  $\sigma$ )

- So we expect the sum to be about N
- However, you have to subtract off the number of parameters in the fit function
  - Eg. Straight line: has 2 free parameters, slope+intercept
    - A fit to 2 data points has  $\chi^2 = 0$  as a line can always be drawn through 2 points. It has 0 degrees of freedom (dof)

## Degrees of freedom

- A fit of a straight line to 3 data points has 1 dof (3 points – 2 fit parameters). There is real information here.
- In general, #dof = N points – M fit parameters
- A “good” fit will have  $\frac{\chi^2}{ndof} \approx 1$
- A bad fit will have a large value
- A very small value indicates your errors are overestimated!
  - This is as bad as underestimating errors!